


Fast Connection - Screwless Spring Type

DT141 and DT142 Series Pitch 2.54mm and 5.08mm Vertical and Horizontal entry


Insert and release wires using a screwdriver in the slot
Terminals and solid wires can be inserted directly without the assistance of the lever.

Part Number	Poles	Pitch mm	Max Current	Max mm ²
32-DT141V-xxP	2 to 24	2.54	4A	0.5
32-DT141R-xxP	2 to 24	2.54	4A	0.5
32-DT142V-xxP	2 to 24	5.08	10A	2.5
32-DT142R-xxP	2 to 24	5.08	10A	2.5




Where xx is the number of poles




32-DT141R-07P




32-DT141V-05P






32-DT141V-06P



32-DT142R-07P



32-DT142V-07P



32-DT142R-04P